ROOM HUMIDITY TRANSMITTER (GSH-110)



Application

"GSH" Room Humidity Transmitters are intended for an electronic Humidity Transmitter to measure the Relative Room Humidity (RH) and convert the measurement into an electric signal.

Equipment Combinations

This unit can be used with all system equipments that can receive output signals 0-10VDC of the detector.

Operating Mode

- Electronic sensing circuit varies signal into $0\sim10$ VDC(within $0\sim100$ % relative humidity)
- Sensing Accuracy is ±3% within usable range of 20~90%RH

Technical Data

SUPPLY VOLTAGE : 24V AC/DC ±20%

• FREQUENCY : 50 or 60Hz

• SENSING ELEMENT : Integrated Circuit

POWER CONSUMPTION : 0.35VA

SENSING RANGE : 0 ~ 100%RH

• ACCURACY at 20° : at 20° 90%Hh within \pm 3%RH • OUTPUT SIGNAL : 0° 10VDC (GSH-010: 0° 1VDC)

SENSING TIME : Approx, 20sec

• AMBIENT TEMPERATURE :

1) On Operation: $-10^{\sim} + 70^{\circ}$ C

2) On Transportation & Storage: -25~+65°C

AMBIENT HUMIDITY :
1) On Operation: below 100%RH

2) On Transportation & Storage: below 95%RH

• WIRING : 3wires, 1.0mm or Shield Cable


WEIGHT : 0.06KgHOUSING : plastic case

PROTECTION CLASS : IP30

Mounting Notes

- The element must not be touched and should be protected dust, water, spray and condensation.
- The sensor element must not be exposed to organic solvents, sylphid bearing materials.
- Select a location approx 1.5 meter above the floor.
- The sensor location should also be reasonably dean and free from damp and condensation.
- Fix with the bolts provided in pull box(50×100 , 100×100)
- To avoid the conductive current the wires should be separated from power lines.
- Use the shield line when wiring.

Wiring Diagram



Dimension

